



STS-110/ET-114 Flight Readiness Review

External Tank Project







Overview

Presenter R. Wetmore/LMSSC-ET/3000

Date March 26, 2002 Page 2

- Limited Life Component Status
 - All within required life through scheduled launch date plus 90 days
- No Significant Changes
- Processing Anomalies
 - Access Arm Interference with Intertank
- Readiness Statement





Access Arm Interference with Intertank

Presenter R. Wetmore/LMSSC-ET/3000		
Date	March 26, 2002	Page 3

Issue

• ET-114 Intertank damaged due to Intertank access arm extensible platform interference

Background

- Extensible platform was left in an extended position
 - Arm impacted Intertank stringers approximately 12" aft of Intertank access door
 - Interference evident by damaged foam on Intertank stringers



Damaged Foam on Intertank Stringers



Foam Removed from Stringers for Inspection







Access Arm Interference with Intertank

Presenter R. Wetmore/LMSSC-ET/3000		
Date	March 26, 2002	Page 4

Actions Taken

- Inspection required to quantify extent of damage
 - Foam trimmed / removed to expose substrate
 - Performed visual inspection using 10x magnification

Inspection Results

- Visual inspection with 10x magnification showed no evidence of crack or crack-like defects
 - Minor contour deviations ('dents') were noted on two of the stringers (Stringers 5 and 6)
- Damaged / trimmed foam area will be repaired using previously approved materials / processes

Rationale for Acceptance

- Stress analysis shows the FS remains greater than 2.0
 - Structural loads at this location are low
- Fracture analysis predicts >5000 cycles necessary to grow a flaw to failure (through-crack equal to width of largest 'dent')
 - Four cycles required





Readiness Statement

Presenter R. Wetmore/LMSSC-ET/3000

Date March 26, 2002 Page 5

The External Tank, ET-114, is certified and ready for STS-110 flight pending completion/closure of open and planned work